

Lochluichart East BESS Appendix 4.1

Technical Appendix, Photographic Records



Plate 1 Existing Forest Access Track



Plate 2 Indicative New Access Track



Plate 3 *Indicative felling area for BESS*



Plate 4 *Aerial Image of Woodland Cover within the Indicative Felling Area*



Plate 5 *Native Woodland (to be avoided)*



Plate 6 *Visibility Splay East Roadside View*



Plate 7 *Visibility Spay East Internal View*



Plate 8 *Visibility Splay West Roadside View*



Plate 9 *Visibility Splay West Specimen Conifer Tree (to be avoided)*



Plate 10 *Visibility Splay West Specimen Broadleaved Tree (to be avoided)*